



Dacia Lodgy

VIN: UU1JSDAC650065289 Diesel 2013

Generat pe 29.04.2025, 11:29

Odometru
✓ Arată bine

Statut legal
✓ Arată bine

Daune
✓ Arată bine

+31 **Surse de date**
Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?

✓ **Nu s-au găsit probleme**
Nu am găsit nicio înregistrare că vehiculul a fost furat.

Notă
Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 11 țări: +5

Iată ce am verificat:

Căutat drept furat ✓ Nu s-a găsit nicio înregistrare

Furat în trecut ✓ Nu s-a găsit nicio înregistrare Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate **verificare finalizată în:**


- România
- Ungaria
- Lituania
- Statele Unite ale Americii
- Cehia
- Slovenia
- Italia
- Slovacia
- Suedia
- Danemarca
- Canada

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

Notă

- Ultimul kilometraj cunoscut: 175.175 km
- Kilometraj mediu pentru modele similare: 201.105 km
- 10 înregistrări ale kilometrajului



Înregistrările odometrelui

12.2013	11 km
05.2015	16.713 km
02.2016	25.075 km
05.2016	27.744 km
06.2016	29.410 km

Înregistrările odometrelui

01.2017	35.911 km
03.2017	39.175 km
05.2020	101.133 km
04.2022	136.807 km
04.2024	175.175 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Notă

Inspecția tehnică a fost transmisă pe 04.2024 în Franța

Legal



Inspecție tehnică periodică (ITP)

A trecut

04.2024

Franța

A trecut cu succes inspecția tehnică

Valabil până la 04.2026



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?



Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 27.324 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Dacia Lodgy 2013

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

24.646 RON

Prețul mediu

27.324 RON

Cel mai mare preț

30.664 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Sugestia carVertical

Acest vehicul are emisii scăzute. Poate se califica pentru taxe mai mici pentru emisii. Verifică reglementările locale ca să vezi dacă se aplică reduceri.

Emisii CO₂

Emisii CO₂ g/km

Până la
120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Emisiile de
CO₂ ale
vehiculului
tău

116 g/km

Clasă **A**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Dacia



Model

Lodgy



Descriere

Lodgy



Tip caroserie

Autovehicul multifuncțional



An de fabricație

2013



Capacitate cilindrică

1,5 l



Putere motor

81 kW (109 cp)



Tip combustibil

Diesel



Cutie de viteze

Manuală



Tip transmisie

Tracțiune față (FWD)



Nr. uși

5



Nr. viteze

6



Nr. locuri

5



Categorie

M1



Omologare

e2*2001/116*0314*69

Echipare

Cum a fost primit de la producător

ACCESSORY SOCKET

WITH ACCESSORY SOCKET 2 (PRIAC2)

ADDITIONAL HEADLIGHTS

FOG LIGHTS (PROJAB)

AIR DUCT TO REAR SEATS

WITH AIR DUCT TO REAR SEA (AIRAR)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

BRAKING ASSISTANCE

ADDITIONAL FITTINGS

WITHOUT SUPPLEMENT (SSEQT)

ADJUSTMENT OF FRONT SEAT BELTS

HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

AIRBAG CANCEL

DECONNEX AIRBAG PASS (AIRBDE)

ANTI-THEFT DEVICES

ALARM 01 (ALAR01)

COLOR OF OUTSIDE MIRROR

BOOSTER EMERGENCY BRAKING (AFURGE)

COMMERCIAL EVENT MANAGEMENT 3

COMPLEMENTARY OBJECT (SANF78)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

COMMERCIAL VERSION SUPPLEMENT1

WITHOUT VERSION COMPLEMEN (SAN713)

COUNTER UNIT

KILOMETRES (KM)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

DOOR OPENING REMOTE CONTROL TYPE

433 MHZ NORMAL DOOR OPENI (SOP02C)

DRIVER SEAT TYPE

DRIVER SEAT WITH BOOSTERC (COREHA)

DRIVING ASSISTANCE

DRIVING ASSISTANCE : VEHI (ADAC)

ECONOMIC DRIVING

COMPLEMENTARY OBJECT (SANE46)

ELECTRONIC STABILITY PROGRAM

WITHOUT DIRECTIONAL STABI (SSESP)

ENGINE PRODUCTION PLANT

(D) VALLADOLID MOTORES (SPAIN) (APV002_D)

FIRE EXTINGUISHER

WITHOUT FIRE EXTINGUISHER (SEXTIN)

FRONT ARM REST

CONTEXT CRITERIOM (SAN111)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

FRONT TYRES

185/65 R15 (88)T, 5.00 J 1 - 5

GEAR SHIFT INDICATOR

COMPLEMENTARY OBJECT (SANE84)

GEOGRAPHIC COUNTRY

COMPLEMENTARY OBJECT (SAN328)

INSIDE DOOR HANDLE

INSIDE HANDLE3 (PGINT3)

INTERNAL NAME

BODY COLOR EXTERIOR REARV (RETC)

COMMERCIAL IDENTITY

WO COMMERCIAL IDENTITY (SSIDCO)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

CONDITIONING

COMPLEMENTARY OBJECT (SAN147)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG: FRANCE (TLFRAN)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 1 (FDIU1)

DOOR SECURITY

CONTEXT CRITERIOM (SAN296)

DRIVER'S AIR BAG

DRIVER AIRBAG 1 (ABCO01)

DUST PROTECTION

WITHOUT DUST KIT (SKTPOU)

ELECTRONIC ARCHITECTURE

ELECTRONIC ARCHITEC T4 (AVARC1)

EMERGENCY CALL AND BREAKDOWN

WITHOUT CALL FONCTION (SSCALL)

EXTERIOR REAR VIEW MIRRORS

2 ELEC OUTSIDE MIRRORS (RETROE)

FRONT AND REAR PROXIMITY RADAR

REAR PROXIMITY RADAR (RDPRAR)

FRONT SEAT BELT PRETENSIONER

FRONT SEAT BELT WITH PRET (PTCAV)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG (ABLAV)

FUEL CAP

CAP WITH KEY (BOUCLE)

GEARBOX PRODUCTION PLANT

(S) SEVILLE (SPAIN) (APV003_S)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 01 (HARM01)

INVARIANT PROCESS SHEET MODEL

NO NAME (SSAPEL)

LEVEL OF NAVIGATION AID

LEVEL 0 TYPE 1 NAVIGATION (NAV0G1)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

MISCELLANEOUS BENEFITS CINQUO

COMPLEMENTARY OBJECT (SANE24)

NAVIGATION/SMARTPHONE IMITATION

COMPLEMENTARY OBJECT (NOG72)

OUTSIDE DOOR HANDLE TYPE

OUTS DOOR HANDLE TYPE2 (PGPRT2)

PASSENGER AIR BAG

PASSENGER AIRBAG (ABPA01)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN593)

POWER STEERING

ELE PUMP POWER STEERING (GEP01)

PRICING

COMPLEMENTARY OBJECT (NOH02)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

REAR HEADREST TYPE

3 FULL REAR HEAD RESTRAIN (3ATRPH)

REAR SEAT TYPE

REAR BENCH SEAT FUNCTIONA (FBANAR)

REAR TYRES

185/65 R15 (88)T, 5.00 J 1 - 5

REAR WINDOW CONTROL

MOTOR UNIT (LVAREL)

ROOF RACK/BARS

SILK-FINISH ROOF BARS (BARSAT)

SEAT BELT REMINDER

WITH SEAT BELT NOT SECURE (ALouc)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

SEATS: 3RD ROW

MODEL ROUTING SHEET (X921MO)

LUGGAGE COVER

DETACHABLE LUGGAGE (CCHBAM)

LUGGAGE ROOM LIGHTING

LIGHTED LUGGAGE ROOM (LUCOF)

MARKETING VERSION

COMMERCIAL VERSION (VEC175)

NAVIGATION MAP

STANDARD MAPPING (MAPSTD)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (SSCEDA)

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING (CA)

POWER ASSISTED STEERING

POWER STEERING (DA)

PRE-INSTALLED LICENSE PLATE

W/O PRE-INST LICENSE PLAT (SSPPLQ)

PROTOTYPE VERSION

CONTEXT CRITERIOM (SAN244)

REAR FOG LIGHTS

REAR FOG LIGHTS (FARBR)

REAR SCREEN WIPERS

WITH REAR SCREEN WIPERS (ELA)

REAR SEATS VIEW

CONTEXT CRITERIOM (SAN616)

REAR WINDOW

HEATED REAR SCREEN (LAC)

ROAD SEVERITY

NORMAL SUSPENSION (SUSNOR)

ROUTING SHEETS COUNTRY

FRANCE (FRAN)

SEAT COVERS

FABRIC SEAT-LINING N 03 (DRAP03)

SEAT TRIMS

VELVET CLOTH (DRA)

SERVICE AHA

0 SEAT - THIRD ROW SEATS (0P3RAN)

SERVICE COUNTRY

COMPLEMENTARY OBJECT (SAN547)

SERVICE TMC

COMPLEMENTARY OBJECT (SANG18)

SPARE WHEEL

NORMAL SPARE (RSNORM)

SPECIAL TECHNICAL FEATURES CODE

CONTEXT CRITERIOM (SAN393)

STEERING SWITCH

STEERING SWITCH 1 (CDVOL1)

STEERING WHEEL MATERIAL

LEATHER STEERING WHEEL (VLCUIR)

STORAGE FOR ACCESSORIES

WITHOUT STORAGE FOR ACCES (SRAGAC)

SUN VISOR ON PASSENGER SIDE

COMPLEMENTARY OBJECT (SAN385)

TECHNICAL EVOLUTION A

COMPLEMENTARY OBJECT (NOG66)

TECHNICAL EVOLUTION C

COMPLEMENTARY OBJECT (NOH10)

TECHNICAL EVOLUTION M

COMPLEMENTARY OBJECT (NOH68)

TOPPED BY TIRES

COMPLEMENTARY OBJECT (SAN470)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

TYPE OF REFRIGERANT GAS

COMPLEMENTARY OBJECT (SANF92)

TYRE PRESSURE DETECTION

WITHOUT TYRE PRESSURE DET (SDPRPN)

VARIOUS ADDITIONAL FEATURES

COMPLEMENTARY OBJECT (SAN482)

VEHICLE PRODUCTION PLANT

(I) TANGIER (MOROCCO) (APV001_I)

VP REAR SEATING LIGHTING

COMPLEMENTARY OBJECT (SAN433)

COMPLEMENTARY OBJECT (SANG16)

SERVICE DONGLE

COMPLEMENTARY OBJECT (NOH14)

SMOKER'S ACCESSORIES

WITH SMOKER ACCESSORIES (AVCACF)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58J)

STEERING WHEEL HEIGHT ADJUSTMENT

HEIGHT ADJUSTABLE STEERING WHEEL (VOLRH)

STEERING WHEEL POSITION

LEFT (DG)

STRIPPING

STRIPPING N01 (DECA01)

TECHNICAL ENVELOPES (SEE OVAL PLATE)

ENVIRONNEMENTAL CONSTRAIN (CEE1)

TECHNICAL EVOLUTION B

COMPLEMENTARY OBJECT (NOH06)

TECHNICAL EVOLUTION D

COMPLEMENTARY OBJECT (NOH16)

TECHNICAL EVOLUTION V

COMPLEMENTARY OBJECT (NOH90)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

TYPE OF FRONT WINDOW WINDER

DRIVER: MOTOR UNIT / PASSENGER: MOTOR UNIT (LVAVEL)

TYPES OF RADIOS

RADIO 45A (RAD45A)

UNDERBODY PROTECTION

WO ANTIGRIT PROTECTION (SKTGRV)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

VEHICULE TRANSFORMATION

COMPLEMENTARY OBJECT (SAND30)

WHEEL DISC PROTECTION

WITHOUT PROTECTIVE REAR B (SPRODI)

WHEEL RIM TYPE

16 ALUMINIUM WHEEL RIMS 1 (RALU16)

WHEELS RIMS

NORMAL WHEEL (RNORM)

WHEEL TRIM

WITHOUT HUBCAP (SSENJO)

WINDOW TINT

TINTED WINDOWS (VT)

Cronologie

S-au găsit 6 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

12.2013 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

05.2014 🇫🇷 Franța



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

07.2017 🇫🇷 Franța



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

05.2020 🇫🇷 Franța



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

04.2022 🇫🇷 Franța



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

04.2024 🇫🇷 Franța



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**